



USB-2514

USB to 4-Port RS-232 Converter

Features

- Hi-Speed USB 2.0 for up to 480 Mbps USB transmission
- Power and data flow indicator for troubleshooting
- Driver Supports Windows 7(32/64-bit)/8 (32/64-bit)/10(64-bit)/11(64-bit)/Linux




Introduction

USB-2514 is USB to 4-port RS-232 converter that provides a simple way add up to four RS-232 ports on your PC. The USB-2514 is support USB 1.1, USB 2.0 standards and easy setting RS-232 transmission speed from 300 bps to 921600 bps.


System Specifications

Interface		
USB	Fully Compliant with the USB 1.1/2.0/3.0	
RS-232	TxD, RxD, RTS, CTS, DTR, DSR, DCD, RI, GND	
Speed	300 bps ~ 921.6 Kbps	
Connector	RS-232	DB9 male x 4
	USB	Type B
LED Indicators		
Power/Communication	Yes	
Power		
Input Voltage Range	Bus-powered	
Power Consumption	4 W	
Mechanical		
Casing	Plastic	
Dimensions (W x L x H)	31 mm x 116 mm x 147 mm	
Environment		
Operating Temperature	-25 °C ~ +75 °C	
Storage Temperature	-30 °C ~ +75 °C	
Humidity	10 ~ 90% RH, non-condensing	

Applications



Dimensions (Units: mm)



Ordering Information

USB-2514 CR	USB to 4-Port RS-232 Converter (RoHS) Includes CA-USB18 Cable
-------------	---

Accessories

USB-2560 CR	Industrial 4-port USB 2.0 Hub (RoHS)
-------------	--------------------------------------